



CONDITION REPORT

TRENCHLESS EQUIPMENT

MAKE: Vernier

DATE: 1-11-24

MODEL: D20x22 Series II

GENERAL OVERALL CONDITION

(Higher Numbers are Better) 1 2 3 4 5

SERIAL:

☐ 1 ☐ 2 ☐ 3 ☒ 4 ☐ 5

HOURS: 3254

INSPECTION RATINGS KEY

YEAR: 2014

5 = Excellent cond.-New or recently replaced parts.

CUSTOMER:

4 = Operates well, shows less than average wear.

CONTACT:

3 = Operates and is in avg. condition for age and hrs, minimal repairs.

PHONE #

2 = Operates but needs repairs.

EVALUATOR:

1 = Repairs necessary prior to use.

DIRECTIONS / CUSTOMER INFO.

ENGINE

NOTES

(Higher Numbers are Better)

1 2 3 4 5 N/A

Fluid level and condition ☐ 1/4 ☐ 1/2 ☐ 3/4 ☒ Full

Perform Oil Sample ☐ YES ☒ NO

Engine Noise ☐ YES ☒ NO ☐

Engine Smoke ☐ YES ☒ NO ☐

Visible Leaks ☐ YES ☒ NO ☐

Gauges Instruments ☐ ☐ ☐ ☒ ☐ ☐

Belts and Pulleys ☐ ☐ ☐ ☒ ☐ ☐

Idle and Throttle Quality ☐ ☐ ☐ ☒ ☐ ☐

Engine Mounts and Slides ☐ ☐ ☐ ☒ ☐ ☐

Radiator / Hoses ☐ ☐ ☐ ☒ ☐ ☐

Any Missing Parts ☐ YES ☒ NO

SAFETY EQUIPMENT

(Higher Numbers are Better)

1 2 3 4 5 N/A

Seat Belt ☐ YES ☒ NO ☐

Operator Presence Switch (seat) ☒ YES ☐ NO ☐

Safety Switches ☐ ☐ ☐ ☐ ☒ ☐

Red Safety Bars/ E- stops ☐ ☐ ☐ ☐ ☐ ☒

Work Lights ☒ YES ☐ NO ☐

Strike Alert / Ground wire ☐ ☐ ☐ ☐ ☒ ☐

Decals In Place / Legible ☒ YES ☐ NO ☐

Any Missing Parts ☐ YES ☒ NO ☐

BODY PANELS

(Higher Numbers are Better)	1	2	3	4	5	N/A
Paint	☐	☐	☐	☐	☒	☐
Panel Dents	☐	YES		☒	NO	☐
Rust	☐	YES		☒	NO	☐
Frame	☐	☐	☒	☒	☐	☐
Any Missing Parts	☐	YES		☒	NO	

OPERATION FUNCTION

(Higher Numbers are Better)	1	2	3	4	5	N/A
Gearbox Rotation at Full RPM	☐	☐	☐	☐	☒	☐
Rollers	☐	☐	☐	☐	☐	☒
Drilling Fluid Shutoff Ball Valve	☐	☐	☐	☐	☒	☐
Throttle Control Front & Rear	☐	☐	☐	☐	☒	☐
Front Vice	☐	☐	☐	☐	☒	☐
Front Vice Cylinder Pins & Frame	☐	☐	☐	☐	☒	☐
Rear Vice	☐	☐	☐	☐	☒	☐
Rear Vice Cylinder Pins & Frame	☐	☐	☐	☐	☒	☐
Rear Vice Tilt	☐	☐	☐	☐	☒	☐
Vice Jaws Damage And Wear	☐	YES		☒	NO	☐
Rear Tilt Cylinder	☐	☐	☐	☐	☒	☐
Right Stake down Up/Down+ Rotation	☐	☐	☐	☒	☐	☐
Rotation	☐	☐	☐	☒	☐	☐
Pins & O rings	☐	☐	☐	☒	☐	☐
Left Stake down Up/Down+ Rotatation	☐	☐	☐	☒	☐	☐
Rotation	☐	☐	☐	☒	☐	☐
Pins & O rings	☐	☐	☐	☒	☐	☐
Console Pivots	☐	☐	☐	☐	☒	☐
Rotation Lever, Self Center	☒	YES		☐	NO	☐
Thrust Lever, Self Center Thrust	☒	YES		☐	NO	☐
Rod Loader Arms In/Out	☒	YES		☐	NO	☐
Water Pump On/OFF	☒	YES		☐	NO	☐
Water Pump GPM Up/Down						
Chain & Chain Pins	☐	☐	☐	☐	☒	☒
Chain Adjustment	☐	☐	☐	☐	☐	☒
Wear Pads (Drive Chuck)	☐	☐	☐	☒	☐	☐
Rack And Pinion	☐	☐	☐	☒	☐	☐
Pinion Gears	☐	☐	☐	☒	☐	☐
Any Missing Parts	☐	YES		☒	NO	

Newer

Newer

Newer

Newer

TRACKS AND FRAME

(Higher Numbers are Better)	1	2	3	4	5	N/A
Right Track Forward/Reverse	☐	☐	☐	☐	☒	☐
Track Chain Rollers	☐	☐	☐	☐	☒	☐
Check Track Sprockets	☐	☐	☐	☐	☒	☐
Left Track Forward/Reverse	☐	☐	☐	☐	☒	☐
Track Chain Rollers	☐	☐	☐	☐	☒	☐
Check Track Sprockets	☐	☐	☐	☐	☒	☐
Rollers	☐	☐	☐	☐	☒	☐
Rubber Pads	☐	☐	☐	☒	☐	☐
Track Adjustment	☐	☐	☐	☐	☒	☐
Rear Outrigger Up/Down	☐	☐	☐	☐	☒	☐
Track Extension	☐	☐	☐	☒	☐	☐
Tilt Pivot	☐	☐	☐	☒	☐	☐
Tilt Cylinder	☐	☐	☐	☒	☐	☐
Track Condition	☐	☐	☐	☒	☐	☐
Any Missing Parts	☐ YES			☒ NO		

UNDER CARRIAGE

(Higher Numbers are Better)	1	2	3	4	5	N/A
Track Frame Cracks, Repairs	☐ YES			☒ NO		
Rollers / Idlers	☐	☐	☐	☒	☐	☐
Sprockets	☐	☐	☐	☒	☐	☐
Any Missing Parts	☐ YES			☒ NO		

ROD AND ROD BOX

(Higher Numbers are Better)	1	2	3	4	5	N/A
Number Of Rods / Size	Number of Rods: <u>41</u>					
Check For Wear %	<u>70</u> %					
Bent Rods #	<u>0</u> #					
Check Threads W/gauge	☐ YES			☒ NO		
Check Shoulders W /gauge	☐ YES			☒ NO		
Rod Wipers / Holder Damage	☐	☐	☐	☐	☒	☐
Rod Box	☐	☐	☒	☒	☐	☐
Top Pins / Bottom Pins	☐	☐	☐	☒	☐	☐
Rod Box Damage	☐	☐	☒	☐	☐	☐
Rod Box Cover	☐	☐	☐	☐	☐	☒
Any Missing Parts	☐ YES			☒ NO		

Size: 2.06
70% good 30% wear
none

New

TOOLING / LOCATOR

(Higher Numbers are Better)	1	2	3	4	5	N/A	
Drill Head	☐ YES			☒ NO		☐	
Starter Rod	☐ YES			☒ NO		☐	
Hex Collar	☐ YES			☒ NO		☐	
Duck Bills	☐ YES			☒ NO		☐	
Reamers	☐ YES			☒ NO		☐	
Reamer Sizes	<u>N/A</u> inches						
Wash Wand	☐	☐	☐	☐	☐	☒	
Locator	☐	☐	☐	☐	☐	☒	SN# _____
Remote	☐	☐	☐	☐	☐	☒	SN# _____
Probes Color	☐	☐	☐	☐	☐	☒	SN# _____
Probes Heat Indicator	☐	☐	☐	☐	☐	☒	
Cones	☐	☐	☐	☐	☐	☒	

CAB

(Higher Numbers are Better)	1	2	3	4	5	N/A	
A/C	☐ YES			☒ NO		☐	<u>no cab</u>
Heater	☐ YES			☒ NO		☐	
Glass	☐	☐	☐	☐	☐	☒	
Wipers	☐	☐	☐	☐	☐	☒	
Doors	☐	☐	☐	☐	☐	☒	
Multi-Function Display	☐	☐	☐	☐	☐	☒	

HYDRAULIC SYSTEM

(Higher Numbers are Better)	1	2	3	4	5	N/A	
Hydraulic Fluid Condition	☐ 1/4	☐ 1/2	☐ 3/4	☒ Full			
Pump Pressure / Flow	PSI.						<u>normal operating</u>
Visible Leaks	☐ YES			☒ NO		☐	
Hoses and Fittings	☐	☐	☐	☒	☐	☐	
Operation of Controls	☐	☐	☐	☒	☐	☐	
Hydraulic Tank and Caps	☐	☐	☐	☒	☐	☐	
Perform Oil Sample	☐ YES			☒ NO			
Salesman: _____							

PICTURES

☒ YES ☐ NO

NOTES